

IKO STRIKE PVC

Technical Data Sheet

PRODUCT INFORMATION

IKO Strike PVC lightning conductor clips are hot air welded to the surface of an IKO Armourplan membrane roofing systems at 1m centers to secure standard lightning protection tape systems where they need to be installed over the roof surface.

The IKO Strike clip is a combination of a high-quality rigid plastic clip attached to a 100mm x 100mm section of polyester reinforced membrane.

Description	Uncoated Tape Clip	Coated Tape Clip
Item Number	30075019	30075017
Tape Size	25mm x 3mm	27mm x 5mm
Box Quantity	50	50
Colour	Mid Grey	Mid Grey
Material	PVC	PVC

FEATURES & BENEFITS

- Provides a cost effective and tidy solution to restraining rooftop lightning protection systems
- Excellent UV resistance and durability
- Excellent mechanical properties and product performance
- Efficient and safe installation
- Secure seam welding quality

INSTALLATION GUIDELINES

IKO Strike clips should be hot air welded to the surface of IKO Armourplan membrane roofing systems using standard hot air welding hand tools. The roof surface should be prepared in accordance with IKO recommendations provided in the installer handbook.

TECHNICAL SUPPORT

Advice is available from IKO Technical Services

Telephone: 01257 255771 Email: technical.cc@iko.com

Appley Lane North Appley Bridge Wigan WN6 9AB

Coney Green Road Clay Cross Chesterfield S45 9HZ Prospect Quarry Grangemill Matlock DE4 4BW t: 01257 255771 e: getintouch.uk@iko.com





ACCREDITATIONS









DISCLAIMER

Whilst every precaution is taken to ensure that the information given in this literature is correct and up to date it is not intended to form part of any contract or give rise to any collateral liability, which is hereby specifically excluded.

IKO reserves the right to amend and/or withdraw this document without notice.

Intending purchasers of our materials should therefore verify with the company whether any changes in our specification, application details, withdrawals or otherwise have taken place since this literature was issued.

